

APPLICATIONS

ROOFS

SOPRATACK FLASHING

TECHNICAL DATA SHEET 210730SCANE

supersedes 210609SCANE)

DESCRIPTION

SOPRATACK FLASHING is a two-component odourless polyurethane adhesive. **SOPRATACK FLASHING** adhesive is used to adhere SBS polymer modified bitumen membranes on flashings and slope surfaces > 3 % (3/8 in per ft).

On low slopes (< 3 % [3/8 in per ft]), use SOPRATACK adhesive.

SURFACE PREPARATION

Surfaces must be dry, clean and free of oil, grease, debris or dirt.

In order to prevent moisture on sanded surfaces, it is recommended to install the cap sheet membrane on the same day as the base sheet membrane. If same-day installation is impossible, saturate the sanded surface with **ELASTOCOL 500**.

APPLICATIONS

Remove the lid from part A (hardener) and the lid from part B (resin). Pour part A into part B.

Using a low speed mixer (200 to 400 rpm), thoroughly mix the entire contents of the container for 4 to 5 minutes before use to obtain a homogeneous consistency.

SOPRATACK FLASHING adhesive is applied using a 4.8 mm (3/16 in) or a 6.0 mm (1/4 in) notched trowel in order to apply a uniform coat as per the recommended coverage rate.

The minimum application temperature is 0 °C (32 °F).

CONSULT THE 2020 EDITION OF THE ROOFER'S GUIDE FOR MORE INFORMATION ON THE VARIOUS APPLICATION METHODS RECOMMENDED BY SOPREMA OR PLEASE CONSULT YOUR SOPREMA REPRESENTATIVE.

PACKAGING

Specifications	SOPRATACK FLASHING		
	Part A	Part B	
Physical state	Liquid	Liquid	
Colour	Brown-black	Brown-black	
Container	3.78 L (1 US gal)	14.78 L (3.9 US gal)	
Coverage rate* Non-porous substrate Porous substrate	0.7 to 0.9 L/m² (1.75 to 2.25 US Gal/100 ft²) 0.9 to 1.1 L/m² (2.25 to 2.75 US Gal/100 ft²)		

Note: Coverage rate may vary depending on the application technique and the substrate condition. (All values are nominal)



Système qualité ISO 9001 Quality system

SOPREMA.US • 1.800.356.3521

SOPREMA.CA • 1.877.MAMMOUTH



APPLICATIONS

ROOFS

SOPRATACK FLASHING

TECHNICAL DATA SHEET 210730SCANE

PROPERTIES

Properties	Standards	SOPRATACK FLASHING	
		Part A	Part B
Density	-	1.01 kg/L (8.4 lb/US gal)	1.27 kg/L (10.5 lb/US gal)
Viscosity, Brookfield at 25 $^\circ\text{C}$ (77 $^\circ\text{F})$	-	12 000 cP	950 000 cP
Solid content	-	100 %	99,5 %
Ultimate elongation	ASTM D412	150 %	
V.O.C.	EPA, Method 24	0 g/L	
Open time	-	15 minutes	
Pot life (after mixing)	-	Approximately 60 minutes	
Curing time	-	24 hours*	

*Curing time was determined under ideal application conditions [25 °C (77 °F) and 50% relative humidity] it will be longer at lower temperatures. Curing time will also varies on the quantity applied. (All values are nominal)

CLEANING

Tools and uncured adhesive can be cleaned with solvents, such as mineral spirits, Varsol, Xylene, etc.

STORAGE AND HANDLING

Up to 12 months in original sealed container. **SOPRATACK FLASHING** adhesive can be stored WITHOUT TEMPERATURE LIMITATIONS. However, to facilitate its application, the adhesive must be kept at all times at a temperature between 10 and 30 °C (50 to 86 °F), 12 hours prior to application. Store in a ventilated place, away from heat and direct sunlight.

For more information, refer to instructions on the container label and relevant safety data sheet (SDS).



TDS-SOPRATACK-FLASHING-Soprema-en.indd



SYSTÈME QUALITÉ ISO 9001 QUALITY SYSTEM

SOPREMA.US • 1.800.356.3521

SOPREMA.CA • 1.877.MAMMOUTH